

# ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE

## ER REGULATORY CONTACT RECORD

**Date/Time:** April 19, 2005, 9:00

**Site Contact(s):** Annette Primrose      Norma Castaneda  
**Phone:** 966-4385      966-4226

**Regulatory Contact:** David Kruchek  
**Phone:** 303 692-3328

**Agency:** CDPHE

**Purpose of Contact:** Historic diesel spill in the B774 area

### Discussion

During culvert removal north of the former location of B774, a diesel spill was encountered at a depth of about 4 ½ feet below the current (and final) ground surface. The exposed material was sampled and a TPH field screen showed a concentration of around 290 ppm. Therefore, the excavation will be backfilled. This information will be included in the storm drain No Further Accelerated Action justification.

**Contact Record Prepared By:** Annette Primrose

### Required Distribution:

M. Aguilar, USEPA  
H. Ainscough, CDPHE  
J. Berardini, K-H  
B. Birk, DOE-RFPO  
L. Brooks, K-H ESS  
G. Carnival, K-H RISS  
N. Castaneda, DOE-RFPO  
C. Deck, K-H Legal  
N. Demos, SSOC  
S. Garcia, USEPA  
S. Gunderson, CDPHE  
S. Johnson, K-H ESS  
M. Keating, K-H RISS  
L. Kimmel, USEPA  
D. Kruchek, CDPHE

J. Legare, DOE-RFPO  
D. Mayo, K-H RISS  
S. Nesta, K-H RISS  
L. Norland, K-H RISS  
E. Pottorff, CDPHE  
A. Primrose, K-H RISS  
M. Roy, DOE-RFPO  
R. Schassburger, DOE-RFPO  
S. Serreze, K-H RISS  
D. Shelton, K-H ESS  
C. Spreng, CDPHE  
S. Surovchak, DOE-RFPO  
J. Walstrom, K-H RISS  
K. Wiemelt, K-H RISS  
C. Zahm, K-H Legal

### Additional Distribution:


